



IF ANY OF THE ORIGINAL WIRE SUPPLIED WITH THIS BOILER MUST BE REPLACED, IT MUST BE REPLACED WITH THE SAME UL WIRE TYPE.

Patterson-Kelley
HARSCO
 East Stroudsburg, PA 18301
 570-476-7261
 www.pkbollers.com

P-K MODU-FIRE® FD 750-2000
ENVI™ Control

2300000518
REV. 0.4

REV.	DESCRIPTION	BY	DATE	ASME CODE	DESIGN PRESS.	TYPE X-RAY	WEIGHT	APPROX.	REV.
0.2	REVISION 1	JS	06-21-08						
0.1	REVISION 2	JS	06-24-08						

TITLE	DATE	FILE	SIZE	PRINT	NO.	REV.
WRG_DIAG_FD_MODU_750-2000_ENVI	04-07-09	D	2300000518			0.4

