





6.2.2 SL-2500 & SL-3000 (208-240V)





**P-K SOLIS™ Gas Fired Boiler**  
**Technical Service 1.877.728.5351**



**Patterson-Kelley, LLC**  
 East Stroudsburg, PA 18301  
 570-476-7261  
 www.pattersonkelley.com

IF ANY OF THE ORIGINAL WIRE SUPPLIED WITH THIS BOILER MUST BE REPLACED, IT MUST BE REPLACED WITH THE SAME UL WIRE TYPE.

**SL2500 - SL3000 208-240 V**  
**WITH NURO® CONTROL**

270100070 (2)  
 REV. B