




### 6.2.3 SL-2500 & SL-3000 (480V)




IF ANY OF THE ORIGINAL WIRE SUPPLIED WITH THIS BOILER MUST BE REPLACED, IT MUST BE REPLACED WITH THE SAME UL WIRE TYPE.

**SL2500 - SL3000 480 V  
 WITH NURO® CONTROL**

2701000071 (1)  
 REV. B



**P-K SOLIS™ Gas Fired Boiler**  
**Technical Service 1.877.728.5351**



**Patterson-Kelley, LLC**  
 East Stroudsburg, PA 18301  
 570-476-7261  
 www.pattersonkelley.com

IF ANY OF THE ORIGINAL WIRE SUPPLIED WITH THIS BOILER MUST BE REPLACED, IT MUST BE REPLACED WITH THE SAME UL WIRE TYPE.

**SL2500 - SL3000 480 V**  
**WITH NURO CONTROL**

**2701000071 (2)**  
**REV. B**